## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,891,108 B2 DATED

: May 10, 2005

INVENTOR(S) : Prindiville et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Title page,

Item [56], References Cited, U.S. PATENT DOCUMENTS, insert

5,475,918	12/1995	Kubota et al
5,696,033	12/1997	Kinsman,
5,715,143	2/1998	McHugh et al
5,789,803	8/1988	Kinsman
5,952,611	9/1999	Eng et al.
5,953,216	9/1999	Farnsworth et al.
5,998,860	12/1999	Chan et al
6,013,535	1/2000	Moden et al.
6,017,776	1/2000	Jiang et al.
6,021,563	2/2000	Heo et al.
6,023,666	2/2000	Jiang et al.
6,048,755	4/2000	Jiang et al.
6,060,339	5/2000	Akram et al.
6,084,311	7/2000	Jiang et al.
6,091,136	7/2000	Jiang et al.
6,091,140	7/2000	Toh et al.
6,098,278	8/2000	Vindasius et al.
6,110,805	8/2000	Schrock et al.
6,111,324	8/2000	Sheppard et al.
6,201,299	3/2001	Tao et al.
6,218,731	4/2001	Huang et al.
6,265,766	7/2001	Moden
6,303,997	10/2001	Lee
6,326,700	12/2001	Bai et al.
6,331,451	12/2001	Fusaro et al
412001200		

### Column 4,

Line 67, "convention slot widths" should be -- conventional slot widths --.

## Column 5,

Line 34, "opening (see" should be -- opening) (see --.

Line 51, "operational die" should be -- operational dies --.

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,891,108 B2 DATED : May 10, 2005

1,100 B2

INVENTOR(S) : Prindiville et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 6,

Line 5, "die sites" should be -- die sites) --.

Line 27, "functional dies sites" should be -- functional die sites --.

Signed and Sealed this

Page 2 of 2

Fourth Day of April, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office